

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - minapur/Kamal Pashan ke ghar to moham Pashan ke ghar tak.

A. For Road

1. Damage Location/Chainage : 0.105 Km
2. Damage Length : 34.20 m (0.0342 Km)
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats & Local sand
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.0342 Km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

[Signature]
18.11.20
Signature

(Name of Inspector)

EE

RWD work Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road	Kamal Paswan ke Ghar to Mohan Paswan ke Ghar Tak
--------------	--

District Muzaffarpur

Block	Minapur
-------	---------

Division Muzaffarpur East-2

Length of Road (in Km)

0.291 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	10.757
2	Sand Filling	0.097
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	10.854
TOTAL COST OF PROJECT IN LACS =		10.854

say 10.85 lac

Ramegh
11/11/2020

JE
RWD

~~A 2 11/11/2~~

AE
RWD

203

EE
RWD

Technically approved for Rs 10.85 lac
(Rupees Ten lac Eighty five thousand only)

1/11/12

SE

RWD work circle
muzaffarpur