

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Vibhakar
2. Name of Block/Road - Kouta/shirnagar to Telhara Bithum Pur Beth

A. For Road

1. Damage Location/Chainage : 0.100 km, 0.150 km, 0.600 km, 0.900 km, 1.2 km, 1.50 km, 1.9 km
2. Damage Length : 0.35525 km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick ball
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.35525 km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


21.11.20
Signature

(Name of Inspector)

EE

RWD work division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Shiv Nagar to Tekwar Bishunpur Path

District Muzaffarpur


Block Katra

Division Muzaffarpur East-2


Length of Road (in Km) 3.020 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.043
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.043
TOTAL COST OF PROJECT IN LACS =		4.043


say 4.04 lac


01/10/2020

JE
RWD



01.10.2020

AE
RWD


11/11

EE
RWD

Technically approved for Rs 4.04 lac
(Rupees four lac four thousand only)


26.12.20

SE

RWD work circle
muzaffarpur