


## FIELD INSPECTION REPORT

Date of Inspection : 01/01/2021		District : Munger
Division : Munger		Length (km): 1.748
Name of the Road : L022-L023 Darjapur Gumbi to Matadik		
Scheme/Programme : MAINTENANCE		P.M.C.S.Y
Package No.: BR-22R-076		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/Maintenance		
Sl.No.	Parameters to be checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not(CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls Slab in Rcc culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
<b>3</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
<b>4</b>	<b>Compliance Histroy</b>	
a)	Status of ATR's & any others	

Overall Rating :

Information board, maintenance board, 8 km found but not maintained 200 m stone & singe not found.

Satisfactory (S)	'SRI'
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

  
 (Signature) 01/01/2020

NAME : M.D. Altaf Anwar

DESIGNATION : T.E.

7