


FIELD INSPECTION REPORT

Date of Inspection : 01/01/2021		District : Munger
Division :		Length (km): 0.637
Name of the Road : L024-L023 - Barmani		
Scheme/Programme : MAINTENANCE		P.M. G.S.Y
Package No.: BR-22R-074		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of : New Connectivity/Up gradation/Maintenance		
Sl.No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No
f)	Contraction Joints provided or not(CC Pavement)	Yes / No
g)	Compaction of flank/slope & raincuts if any	Yes / No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/ SRI / U
b)	Condition of Abutment & Wing walls Slab in Rcc culverts	S/ SRI / U N/A
c)	Condition of railings/slab/approach for Bridges	S/ SRI / U N/A
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes / No
4	Compliance Histroy	
a)	Status of ATR's & any others	

Overall Rating : *Main information board, maintenance board found but not maintained. 100 K.M 3 200 ; lineal board not found.*

Satisfactory (S)	✓	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		


 (Signature) 01/01/2021 J.E.

NAME : *MD. ALI ANWAR*

DESIGNATION : *J.E.*