FIELD INSPECTION REPORT

Date of	f Inspection: 01/01/2021 District: Munger	2
Divisio	n: Munger Length (kin). 1.277	
	of the Road: Lo32-To2 Boisnoth Pothoi	
	e/Programme: MAINTENANCE P.M. G.S.Y. Road Id No.:	
ackag	e No Br. 227 O.S. Arriance	
	1 / / Mountonance	*
	New Connectivity/Up gradation/Maintenance Parameters to be checked	Remarks
Sl.No.	Pavement	, , , , , , , , , , , , , , , , , , , ,
1		3/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
(c)	Riding Quality	45/U
d)	Road Camber	- 27 3
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
- -		YES/No
f)	Contraction Joints provided or not(CC Pavement)	Yes / No
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	S/SRI/
a)	Condition of head walls in Hume pipe culverts including its painting	S/ SRI /
b)	Condititon of Abutment & Wing walls Slab in Rcc culverts	
c)	Condition of railings/slab/approach for Bridges	S/ SRI /
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/
4	Compliance Histroy	
-) i	Status of ATR's & any others	Kound but

Overall Rating: 14.M, 200M & himse not found.

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U) (Signature) 101 76

NAME:

MD. Altat Anwor.
1: S.E.

DESIGNATION: