


FIELD INSPECTION REPORT

Date of Inspection : 03/01/2021		District : Munger
Division : Munger		Length (km): 0.465
Name of the Road : REO Road Kalwa at Samudai Bhawan to River Road via vibul Patel house.		
Scheme/Programme : MAINTENANCE MNP		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
SLNo.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not(CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/ SRI / U
b)	Condition of Abutment & Wing walls Slab in Rcc culverts	S/ SRI / U N/A
c)	Condition of railings/slab/approach for Bridges	S/ SRI / U N/A
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance Histroy	
a)	Status of ATR's & any others	

Overall Rating : *Main information board found but not maintained. Km, 200m and single board not found.*

Satisfactory (S)	✓	'S'
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		


 (Signature) 03/01/2021 JE

NAME : MD. Altaf Anwar
 DESIGNATION : S.E