

FIELD INSPECTION REPORT

Date of Inspection : 28/11/20 District: PURNIA
 Division: DHAMDAH Length (km): 1.20 KM
 Name of the Road: Bivek choud Mohanpur to Shobiniy's base.
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road function condition	S/U
b)	Condition of Surfacing	S/U
c)	Rolling Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRL
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRL
c)	Condition of railings/slab/approach for Bridges	S/SRL
3.	Road Furniture	
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature) 28/11/20

CHAUHAN KUMAR
 NAME: A-E RUPAULI