

FIELD INSPECTION REPORT

Date of Inspection : 06-01-2021		District : East Champaran	
Division : Chakia		Length (Km): 2.30 Km	
Name of the Road : PMGSY Road Kuriya Shu mandir to Bishu pura			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S	
a)	Road Junction condition	SRI	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	—	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—	
f)	Contraction Joints provided or not (CC Pavement)	yes	
g)	Compaction of flank/slope & raincuts if any	NO.	
2.	Cross Drainage	—	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—	
c)	Condition of railings/slab/approach for Bridges	—	
3.	Road Furniture	—	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	SRI	
4.	Compliance History	—	
a)	Status of ATR's & any others	—	

Overall Rating :	Satisfactory (S)	SRI
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

NAME :
DESIGNATION :

A.E. Chakia
06/01/2021

(Signature)