


FIELD INSPECTION REPORT

| Date of Inspection : 07.01.2021 | | District : East Champaran | |
|--|---|--|--|
| Division : Chakia | | Length (Km): 0.80 | |
| Name of the Road : NH-28 Bara chakia to Prathmik Vidyalay Ogsha Tala | | | |
| Scheme/Programme : | | MAINTENANCE | |
| Package No.: | | Road ID No.: | |
| Status of the Project : | | Ongoing/Completed/Under Maintenance | |
| Work is a case of : | | New Connectivity/Up Gradation/ Maintenance | |
| Sl. No. | Parameters to be checked | Remarks | |
| 1, | Pavement | | |
| a) | Road Junction condition | - | |
| b) | Condition of Surfacing | - | |
| c) | Riding Quality | - | |
| d) | Road Camber | - | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | SRI | |
| f) | Contraction Joints provided or not (CC Pavement) | Y | |
| g) | Compaction of flank/slope & raincuts if any | SRI | |
| 2, | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | - | |
| b) | Condition of Abutment & Wing walls, Slab in RCC Culverts | - | |
| c) | Condition of railings/slab/approach for Bridges | - | |
| 3, | Road Furniture | | |
| a) | Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained | SRI | |
| 4, | Compliance History | | |
| a) | Status of ATR's & any others | | |

| | | |
|------------------|---|-----|
| Overall Rating : | Satisfactory (S) | - |
| | Satisfactory but requires improvement (SRI) | SRI |
| | Unsatisfactory (U) | - |


 (Signature) 7/1/20
 J.E.

NAME :

DESIGNATION :