

FIELD INSPECTION REPORT

Date of Inspection : 07.01.2021		District : East Champaran	
Division : Chakia		Length (Km): 3.00	
Name of the Road : REO Path Siridhiya via Prathmik Vidyalay Mahaganj to			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1,	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S	
f)	Contraction Joints provided or not (CC Pavement)	Y	
g)	Compaction of flank/slope & raincuts if any	SR1	
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	S	
c)	Condition of railings/slab/approach for Bridges	-	
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	SR1	
4,	Compliance History	-	
a)	Status of ATR's & any others	-	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires improvement (SR1)	SR1
Unsatisfactory (U)	-

(Signature) 7/1/20
J.C.

NAME :
DESIGNATION :