

FIELD INSPECTION REPORT

Date of Inspection : 05/01/2019		District : East Champaran	
Division : Chakla		Length (Km): 4.998.	
Name of the Road : Koyla Belwa Bazar via Pathmik Vidhalay Koyla Belwa Mushar, P.O. to Bazar the.			
Scheme/Programme : MMGSY (M)		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1,	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing	- S -	
c)	Riding Quality	- S -	
d)	Road Camber	- S -	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	- S -	
f)	Contraction Joints provided or not (CC Pavement)	- Yes -	
g)	Compaction of flank/slope & raincuts if any	- Yes -	
2,	Cross Drainage	- S -	
a)	Condition of head walls in Hume pipe culverts including its painting	- SRI -	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	- SRI -	
c)	Condition of railings/slab/approach for Bridges	- S -	
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	- SRI -	
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	SRI
Unsatisfactory (U)	

Abhi
05/01/2019
JE

NAME :

(Signature)

DESIGNATION :