

FIELD INSPECTION REPORT

Date of Inspection :	05/01/2021	District:	East Champaran
Division :	WORKS DIVN DHAKA	Length (km):	2.346 km
Name of the Road:	Khorha to Hasuaha Tola		
Scheme/Programme:	MAINTENANCE	Mukhyamantri Gram Sambar	yojana
Package No.:	Road Id No.: 31708617002		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	✓S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U } N-A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	N-A	

Overall Rating :

Satisfactory (S)	✓S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: SANJAY KUMAR
DESIGNATION: JE

06/01/2021
(Signature)

06/01/2021
JE/Chiraiya