

# FIELD INSPECTION REPORT

|                                                               |                      |
|---------------------------------------------------------------|----------------------|
| Date of Inspection : 21.12.20                                 | District: Nalanda    |
| Division : 14155                                              | Length (km): 5.24 Km |
| Name of the Road: Etanagar Jehnabad Road to Gaudesfort        |                      |
| Scheme/Programme: MAINTENANCE                                 |                      |
| Package No.: B6-246012                                        | Road Id No.:         |
| Status of the Project: Ongoing/Completed/Under Maintenance    | Maintenance          |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | mainten              |

| Sl. No. | Parameters to be checked                                                                                              | Remarks    |
|---------|-----------------------------------------------------------------------------------------------------------------------|------------|
| 1.      | Pavement                                                                                                              |            |
| 1)      | Road Junction condition                                                                                               | S/U S      |
| 2)      | Condition of Surfacing                                                                                                | S/U S      |
| 3)      | Riding Quality                                                                                                        | S/U S      |
| 4)      | Road Camber                                                                                                           | S/U S      |
| 5)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                          | Yes/No Yes |
| 6)      | Connection Joints provided or not (CC Pavement)                                                                       | Yes/No Yes |
| 7)      | Compaction of flank/slope & rainouts if any                                                                           | Yes/No Yes |
| 8)      | Cross Drainage                                                                                                        |            |
| 9)      | Condition of head walls in Hume pipe culverts including its painting                                                  | S/SR/U S   |
| 10)     | Condition of Abutment & Wing walls, Slab in RCC culverts                                                              | S/SR/U S   |
| 11)     | Condition of railings/slab/approach for Bridges                                                                       | S/SR/U S   |
| 12)     | Road Furniture                                                                                                        |            |
| 13)     | Whether sign boards/informatory/cautionary Board/ken & 200m stones/Pavement road markings are provided and maintained | Yes/No Yes |
| 14)     | Compliance History                                                                                                    |            |
| 15)     | Status of ATR's & any others                                                                                          | NO         |

Overall Rating :

|                                             |              |
|---------------------------------------------|--------------|
| Satisfactory (S)                            |              |
| Satisfactory but requires Improvement (SRI) | Satisfactory |
| Unsatisfactory (U)                          |              |

NAME: Pooja Kumar Arora  
J.E

Signature:  
21.12.20