FIELD INSPECTION PEROPT

Da	te of Inspection: 05-0/- 8-0/ Photos		
UN	wion: Danielle Samasti	200	
Val	me of the Road: 1.70 KM	i	
Sch	eme/Promise Squak to Mixianya (na)	M	
Pac	Kage No.	· · · · · · · · · · · · · · · · · · ·	
Sta	tus of the Project: Ongoing/Completed/Under Maintenance		
Wo	rk is a case of: New Connectivity/Up gradation/ Maintenance	. [
Sh	Parameters to the checked	Romarks	
	ement .		
8	Road Junction condition	√S/U	
b	Condition of Surfacing	√S/U	
С	Riding Quality	,25/U	
ď		√S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_Xes/No	٠.
<u>f)</u>	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Brainage No Provision of co work	in Estima:	He.
<i>a)</i>	Condition of head walls in Hume pipe culverts including its painting	S/SRI/V	
<i>b</i>)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SPA/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/Li	
3.	Road Engaiture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compleme History	h	
a)	Status of ATR's & any others \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	ATR Rend	ng
Overall F	Cating :		
CACIUII	Satisfactory (5)	5_1	
	Satisfactory but requires improvement (SRI)		
	Unsatisfactory (U)		

NAME: Rowi Ramah DESIGNATION: J-E

(Signature) 5-01-2021