

# FIELD INSPECTION REPORT

|                        |                                            |              |       |
|------------------------|--------------------------------------------|--------------|-------|
| Date of Inspection :   | 22/12/20                                   | District:    | 6949  |
| Division :             | MAHARASHTRA                                | Length (km): | 1.250 |
| Name of the Road:      | T02 to Chavara                             |              |       |
| Scheme/Programme:      | MAINTENANCE                                | GTSNY.       |       |
| Package No.:           | Road Id No.:                               |              |       |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |       |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |       |

| Sl. No. | Parameters to be checked                                                                                             | Remarks                     |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------------------------|
| 1.      | Pavement                                                                                                             |                             |
| a)      | Road Junction condition                                                                                              | S/U - S                     |
| b)      | Condition of Surfacing                                                                                               | S/U S                       |
| c)      | Riding Quality                                                                                                       | S/U S                       |
| d)      | Road Gamber                                                                                                          | S/U                         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No                      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No                      |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No <i>damaged to 4m</i> |
| 2.      | Cross Drainage                                                                                                       |                             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U SRI                 |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U                     |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U                     |
| 3.      | Road Furniture                                                                                                       |                             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained | Yes/No                      |
| 4.      | Compliance History                                                                                                   |                             |
| a)      | Status of ATR's & any others                                                                                         |                             |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Subendrakr  
22/12/20 J.E

Subendrakr  
22/12/20  
(Signature)

NAME: