

FIELD INSPECTION REPORT

Date of Inspection: 8-1-21		District: GAYA	
Division: Nirmalpur-Balharani		Length (Km.): 0.50	
Scheme/Programme: J.T.S.M.Y		MAINTENANCE	
Package No.: Bhutan to 10		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1 Pavement			
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of FCC Pavement.	Yes	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes	Yes/No
2 Cross-Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRUU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRUU
c)	Condition of railings/slab/approach for Bridges	NA	S/SRUU
3 Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes	Yes/No
4 Compliance History			
a)	Status of ATRs & any others.	No ATR	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Chhotepal
8-1-21
J.E