

FIELD INSPECTION REPORT

Date of Inspection :	6.1.21	District:	Amangalad
Division :	Amangalad	Length (km):	3.05 km
Name of the Road:	1028 to Rasolha (Track-22)		
Scheme/Programme:	MAINTENANCE		
Package No.:	PR-D2R-592	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/I
b)	Condition of Surfacing	S S/I
c)	Riding Quality	S S/I
d)	Road Camber	S S/I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U
c)	Condition of railings/slab/approach for Bridges	S SRI U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S


6.1.21
(Signature)

NAME: