


FIELD INSPECTION REPORT

2.12.20

Date of Inspection :	<u>Aurangabad</u>	District:	<u>Aurangabad</u>
Division :	<u>Aurangabad</u>	Length (km):	
Name of the Road:	<u>Lo86 - To 3 Deo Amba Road to Ratiharp</u>		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	No	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	—	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m yes	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others	<u>Bushes found in Road</u>	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 2.12.20
 (Signature)
Rupinder

NAME: