

FIELD INSPECTION REPORT


Date of Inspection : 2.12.20	District: Aurangabad
Division : Aurangabad	Length (km): 2.00 Km
Name of the Road: LD86 - Tol Risiyap to Mohanpur	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	-	Yes/No
g)	Compaction of flank/slope & raincuts if any	flank damaged at 1.00 Km SRI	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	-	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m yes	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others	flank damaged at two place	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:


 2.12.20
 AE
 (Signature)
 Kunturba