

FIELD INSPECTION REPORT

Date of Inspection :	District:	
Division :	Length (km):	
Name of the Road:	LD 37 - LD 36 to Aoti	
Scheme/Programme:	MAINTENANCE	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	


Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	No	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m yes	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)


 2.12.20
 AE
 (Signature)

NAME: