

FIELD INSPECTION REPORT

5.560541
84.369484
3600.0 m
01-2021 16:05
YA TIYAR PATH T03 TOSHIOBALA TOLA CH1.300KM

District: Phajpur

Length (km): 1.5 km

Road Id No.: 10407002074

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

S.No.	Parameters to be checked	Remarks
1.	Pavement	
	Road Junction condition	S/U S
	Condition of Surfacing	S/U S
	Riding Quality	S/U S
	Road Camber	S/U S
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	No
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

Powered by
2021
JC