

# FIELD INSPECTION REPORT

old mmasx (SC)

Inspection : 07/11/2021 District: Bhosapur  
 R.W. 7.5m to 10m Length (km): 1.70 km  
 Name of the Road: Bahuwa Talar road to Pulai Tark

Scheme/Programme: MAINTENANCE  
 Package No.:  
 Road Id No.: 10401713024  
 Status of the Project: Ongoing/Completed/Under Maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance

| Sl. No. | Parameters to be checked                                                                                        | Remarks                |
|---------|-----------------------------------------------------------------------------------------------------------------|------------------------|
| 1.      | Pavement                                                                                                        |                        |
| a)      | Road Junction condition                                                                                         | S/U S                  |
| b)      | Condition of Surfacing                                                                                          | S/U S                  |
| c)      | Riding Quality                                                                                                  | S/U S                  |
| d)      | Road Camber                                                                                                     | S/U S                  |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | Yes/No                 |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | Yes/No                 |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | Yes/No                 |
| 2.      | Cross Drainage                                                                                                  |                        |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | S/SRI/U SRI            |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | S/SRI/U SRI            |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | S/SRI/U SRI            |
| 3.      | Road Furniture                                                                                                  |                        |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m Yes/No NO missing |
| 4.      | Compliance History                                                                                              |                        |
| a)      | Status of ATR's & any others                                                                                    |                        |

Overall Rating :  
 Satisfactory (S)  
 Satisfactory but requires Improvement (SRI) SRI  
 Unsatisfactory (U)

Signature: 7/11/2021  
 Date: 07/11/2021

NAME: