FIELD INSPECTION REPORT

Date of Inspection :		Co 1	District :	Munger 0.350	/
		your Tarapur	Length (Km):	0.350	KM
	the Road :	Loss to yad	an Sharmo	Tola.	
Scheme/F	rogramme :	MAINTENANCE V			
Package No. :			Road Id No. :		
Status of the Project :		Ongoing/Completed/Under	Maintenance		
Work is	a case of :	New Connectivity/Up grada	tion/Maintenance		
Sl. No.	d. No. Parameters to be checked		ed	Remarks	
1	Pavement			6	
a)	Road Junction condition			VS/U	
b)	Condition of Surfacing			VS/U	
c)	Riding Quality			S/U	
d)	Road Camber			√S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drain	nage			
a)	Condition of head walls in Hume pipe culverts including it painting			S/SRI/U	-
b)	Condition o	f Abutment & Wing walls, Sla	ab in RCC culverts	S/SRI/U	-
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	-
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance History				
a)	Status of ATR's & any others			NOATR	

Satisfacory but requires Improvement (SRI)

Unsatisfactory (U)

NAME: AMRENDRA DESIGNATION: KUMBR

Signature)