

FIELD INSPECTION REPORT

Date of Inspection	03/01/2021	District:	Purnia.
Division:	Dhamdaha.	Length (km):	3.0 km
Name of the Road:	Maktapar to Sora 70/9.		
Scheme/Programme:	MAINTENANCE		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a.	Road Junction condition	S
b.	Condition of Surfacing	S
c.	Riding Quality	S/U
d.	Road Camber	S/U
e.	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f.	Contraction Joints provided or not (CC Pavement)	Yes/No
g.	Compaction of flank/slope & raincuts if any	Yes/No
2.	Crass Drainage	
a.	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b.	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c.	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a.	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No by ATR

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

[Signature]
03/01/2021
(Signature)

NAME: Kamal Narayan Sharma
Junior Engineer