


FIELD INSPECTION REPORT

Date of Inspection :		District : East Champaran
Division : Chakla		Length (Km): 0.900 Km
Name of the Road : Murgu Farm Parari to LOSS Hajam tal.		
Scheme/Programme :		MAINTENANCE ✓
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance ✓
Work is a case of :		New Connectivity/Up Gradation/ Maintenance ✓
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	-
c)	Riding Quality	SRI
d)	Road Camber	-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	SRI
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	S
4,	Compliance History	-
a)	Status of ATR's & any others	-

Overall Rating :	Satisfactory (S)	-
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	-


 (Signature) A.E.

NAME :

DESIGNATION :