FIELD INSPECTION REPORT

Date of Inspection: 06 01/2021			District : East Champaran	
Division : Chakia Length (Km): 0.800 k			n· .	
Name of the Road: Bhuwan chapta to 1033.				
Scheme/Programme : MAINTENANCE				
Package No.: Road ID No.:				
Status of	the Project :	Ongoing/Completed/Under Maintenance		
Work is a	case of :	New Connectivity/Up Gradation/ Maintenance		
SI. No.	Parameters to be checked			Remarks
1,	Pavement			
a)	Road Junction condition			-S -
b)	Condition of Surfacing			- S -
c)	Riding Quality			-5-
d)	Road Camber			-S-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			- Yes.
f)	Contraction Joints provided or not (CC Pavement)			- Yes-
g)	Compaction of flank/slope & raincuts if any			-SR1- ·
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			-SRI-
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			-581-
c)	Condition of railings/slab/approach for Bridges			-SRI-
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			-SRI-
4,	Compliance History			
a)	Status of ATR's & any others			
	Overall Rating :	Satisfactory (S)		

Satisfactory but requires improvement (SRI)

06/01/2021

Unsatisfactory (U)

(Signature)

NAME:

DESIGNATION:

SRI