

FIELD INSPECTION REPORT

Date of Inspection : 29.12.20		District: East Champaran
Division : Baran		Length (km): 2.182
Name of the Road: L039 - Toq to Gadidani		
Scheme/Programme: MAINTENANCE		PMGSY
Package No.: BR-11R-646		Road Id No.: 3170 850 2070
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓S/U
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	N/A
2.	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	N/A
a)	Whether sign boards/informatory/cautionary, Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(S)
Unsatisfactory (U)	

29.12.20

(Signature)

NAME: Nitish Kumar Singh

DESIGNATION: Junior Engineer, Baran