

FIELD INSPECTION REPORT

Date of Inspection: 05.09.21		District: East Champaran	
Division: Rayachoti		Length (km): 0.833	
Name of the Road: L24 To 3 to Lachhimpur			
Scheme/Programme: MAINTENANCE		P-1434	
Package No.: BR-11P-698		Road Id No.: 317050502072	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	/S/U
b)	Condition of Surfacing	/S/U
c)	Riding Quality	/S/U
d)	Road Camber	/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	/S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	/S/SR/U
c)	Condition of railings/slab/approach for Bridges	/S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating: _____

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Mithilesh Kumar Singh

DESIGNATION: Junior Engineer, Road and