

# FIELD INSPECTION REPORT


Date of Inspection:		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 1.944	
Name of Road : T03 to Boriaali			
Scheme / Programme:		MAINTENANCE P.mbsy	
Package No: BR-302-506		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	

Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S.R.I
c)	Riding Quality	U
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	U
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridge	
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	R.I
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating : U

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
✓ Unsatisfactory(U)	

Ramesh Kumar Sgl  
JE

  
 23.12.2020  
 (Signature)

NAME:  
DESIGNATION :