


# FIELD INSPECTION REPORT

Date of Inspection: 23.12.2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 2.41	
Name of Road : LO71 to Karhadha.			
Scheme / Programme: MAINTENANCE		P.M.G.S.Y	
Package No: BR-302 548		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks	
1	<b>Pavement</b>		
a)	Road Junction Condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S	
f)	Constraction Joint provided or not(CC Pavement)	-	
g)	Compaction of flank/slope & raincuts if any	S	
2	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	NA	
c)	Condition of railings/slab/approach for Bridge		
3	<b>Road Furniture</b>		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S.R.I	
4	<b>Compliance History</b>		
a)	Status of ATR's & any others	No	

Overall Rating : S.R.I

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

  
 23.12.2020

(Signature)

Ramesh Kumar Singh

NAME:

DESIGNATION :

J E