

# FIELD INSPECTION REPORT

Date of Inspection: 28/12/XX	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 0.700	
Name of Road: Soy to Parv West Tola		
Scheme / Programme: MAINTENANCE		
Package No:	Road Id No: 675NY	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	U
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N/A U
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

*Deepak Ch. Sinha*  
28/12/XX  
(Signature)

NAME:

Deepak Ch. Sinha

DESIGNATION :

J-E