## FIELD INSPECTION REPORT

Date of	Inspection: 17/12/20   District: Bhagalpur			
Divisio	n: Bhagalpur   Length (Km):	1.130		
Name o	f the Road: Banansi sharma college more to	Pahar Tola		
Scheme	/ Programme:   MIMUSY (CC)			
Package	No.:   Road Id No.: 26	10320	1333	
Status of	f the Project:   Ongoing / Completed / Under Maintenance			
Work is	a case of:   New Connectivity / Up gradation / Maintenan	ce		
SL. Nö.	Parameters to be checked	Parameters to be checked Remarks		
1.	Pavement		1,127	
a)	Road Junction condition	S/U		
b)	Condition of Surfacing	S/U		
c)	Riding Quality	S/U		
d)	Road Camber	S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No		
g)	Cpmpaction of flank/slope & raincuts if any	Yes / No	1	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U		
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	Scrati	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road Furniture	- 数数位		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No		
4.	Compliance History			
a)	Status of ATR's & any others			
erall Ra	ting:	hina da		
	Satisfactory (S)		5	
	Satisfactory but requires Improvement (SRI)			
1989 94	Unsatisfactory (U)	1613 Sale /		

Note:

NAME: NEERAJ KUHAR

DESIGNATION: JE

1HIN Signature