

FIELD INSPECTION REPORT

Date of Inspection:	07-01-2021	District: JEHANABAD
Division:	Jehanabad	Length (km):
Name of the Road:	NH110 Mandel Kara Karko Chandur Tola via Tiwari bigha	
Scheme/Programme:	NAWARD	MAINTENANCE
Package No:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under gradation/Maintenance	
Work is a case of:	New Connectivity/Up gradation/Maintenance	
S.N	Parameters to be checked	Remarks
1.	Payment	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

Signature
07/01/21

NAME: Arjun Chaudhary
DESIGNATION: JE