FIELD INSPECTION REPORT

Date of Inspection: 03 01 2021			District:	Mynger	
Division: Munger Name of the Road: Malgama Panchayat One of the Road: Malgama Panchayat		Munaed	Length (km):	0.250	
Name o	of the Road : Make	Jama Panchayat me	L Kanya vidyalay.	se sharma t	sha tall Park.
Scheme	e/Programme :	MAINTENANCE	NABAIZD	,	
Packag			Road Id No.:		
Status of the Project: Ongoing		Ongoing/Complete	ng/Completed/Under Maintenance		
Work is a case of: No			New Connectivity/Up gradation/Maintenance		
Sl.No.	Parameters to be checked Remarks				
1	Pavement				
a)	Road Junction condition				
b)	Condition of Sur	\\$/U			
c)	Riding Quality	45/U			
d)	Road Camber	√S/U			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes / No				
f)	Contraction Joints provided or not(CC Pavement)				Yes / No
g)					Yes/No
2	Cross Drainage				1100440 -
a)	Condition of head walls in Hume pipe culverts including its painting			S/SkI/U	
b)	Condititon of Abutment & Wing walls Slab in Rcc culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/ SRI / U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m				
	stones/Pavement road markings are provided and maintained				Yes/No
4	Compliance Hi	stroy	ta an in the material		
a)	Status of ATR's	& any others			

Hume pipe farapet not Printed.

Overall Rating:

Satisfactory (S)	V	3,
Satisfactory but requires Impr	ovement (SRI)	
Unsatisfactory (U)	0 8	
		2021

(Signature)

NAME: MD. AULA Anword
DESIGNATION: TE