FIELD INSPECTION REPORT

Date of In	spection: 17/12/20 District: Bhagalpur			
Division:	Bhagalpur Length (Km):	<u> </u>	The second second	
Name of the	he Road: Main Road RED to Kishanpun			
Scheme / I	Programme: MMUsy(sc)	ARREST		
Package N	To.: Road Id No.: 257	6320	1055	
Status of the	he Project: Ongoing / Completed / Under Maintenance			
Work is a	case of: New Connectivity / Up gradation / Maintenan	ce		
SL. Nö.	No. Parameters to be checked		Remarks	
1.	Pavement		- 12 to	
a)	Road Junction condition	S/U		
b)	Condition of Surfacing	S/U	-	
c)	Riding Quality	S/U	1.1	
	Road Camber	S/U	3	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No		
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	1 3	
g)	Cpmpaction of flank/slope & raincuts if any	Yes/No	1 1	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U		
b) (Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	6.10	
c) (Condition of railings/slab/approach for Bridges	S/SRI/U	Jan 1	
3. I	Road Furniture			
a) V	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No		
4. C	Compliance History		1	
a) St	tatus of ATR's & any others			
erall Ratin	ng:	- The second	is register to the second	
S	atisfactory (S)	(5,		
S	atisfactory but requires Improvement (SRI)	7 466		
	nsatisfactory (U)	25.44		

Note:

NAME: NEERAI KUNAR

DESIGNATION: 16

THINK