FIELD INSPECTION REPORT

Date of	Inspection: 17/1/10 District : Bhagalpur	n en	
Division	n: Bhagalpur Length (Km): 0.25	76	
Name o	f the Road: RCD Road to Lattipun (SC)		- 07
Scheme	/Programme: MMGSY(SC)		
Package	No.: Road ld No.: 207	03201	3 (1
Status of	f the Project: Ongoing / Completed / Under Maintenance	ALP THE TANK	
	a case of: New Connectivity / Up gradation / Maintenand	ce	
SL. No. Parameters to be checked		Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	THE STATE OF
b)	Condition of Surfacing	S/U	
(c)	Riding Qualify	S/U	展
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Cpmpaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others		
verall Ra	ating:		
	Satisfactory (S)	1 1 1	
37	Satisfactory but requires Improvement (SRI)	SRI	
Sala Sala	Unsatisfactory (U)		

Note: Earth Filling in Flank needs.

NAME: NEERAT KUHAR

DESIGNATION: JE

Signature