


FIELD INSPECTION REPORT

Date of Inspection : 07.01.2021		District : East Champaran	
Division : Chakla		Length (Km): 1.324	
Name of the Road : Madhuban Dwd Patil kishori Ben ke ghar Se Babu Tola Baragobind			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
		Remarks	
Sl. No.	Parameters to be checked		
1,	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		
c)	Condition of railings/slab/approach for Bridges		
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained		
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating	Satisfactory (S)	-
	Satisfactory but requires improvement (SRI)	-
	Unsatisfactory (U)	U


 (Signature) 7/1/20
 J. E.

NAME :

DESIGNATION :