


FIELD INSPECTION REPORT

Date of Inspection : 07.01.2021		District : East Champaran	
Division : Chakia RWD (L)		Length (Km): 0.816	
Name of the Road : PMSY Path Kuriya Hanuman Mandir to Noniadi			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S	
a)	Road Junction condition	SRI	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)	Y	
g)	Compaction of flank/slope & raincuts if any	SRI	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	—	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—	
c)	Condition of railings/slab/approach for Bridges	—	
3.	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	S	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	—
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	—


 (Signature) 07/01/2021
 A. E.

NAME :

DESIGNATION :