FIELD INSPECTION REPORT

Date of Inspection: 23.12.2020	District: Samastipur	a la
Division: RWD Dalsinghsarai	Length(km): の・その	
Name of Road: PMUSY Sahpuv	se Nawaz Chowk to	Brahman tala
Scheme / Programme: MAINTENAN	CE SITSH	ን .
Package No:	Road Id No:	
Status of the Project: Ongoing/Complete		
	rity/ Up gradation/ Maintenance	
Parameters to be Checked		Remarks
Pavement		
Road Junction Condition		S
Condition of Surfacing		2
Riding Quality		3
Road Camber		ک
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		S
aggregates in case of CC Pavement Construction Joint provided or not(0)	CC Pavement)	
Compaction of flank/slope & raincuts if any		R.E
Cross Drainage		
Condition of head walls in Hume pi including its painting	pe culverts	NA
Condition of Abutment & Wing wal	lls, Slab in RCC culverts	711
Condition of railings/slab/approach	for Bridge	
Road Furniture	The same was a series of the same of the s	
Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		RI
Compliance History		法判决文学等 等
Status of ATR's & any others		No
Overall Rating :	S. R. I	

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

23.12.2020 (Signature)

Rament Kumar Syl

NAME:

DESIGNATION: