

# FIELD INSPECTION REPORT

Date of Inspection : 05/01/2021	District: East Champaran
Division : WARD Divn DHAKA	Length (km): 0.558km
Name of the Road: Katkuiya Brita Jola to Dhaka PWD road	
Scheme/Programme: MAINTENANCE	GTSNY
Package No.:	Road Id No.: 31708601809
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U Painting Required
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓ Painting required.
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Note - Maintenance work not done by Contractor

06/01/2021  
(Signature)

NAME: SANJAY KUMAR 06/01/2021  
DESIGNATION: J.E JE/chiraiya