

FIELD INSPECTION REPORT

Date of Inspection: 28/12/17		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 0.510
Name of Road : Pachpaina rd. to Dam Tale Muslim Tola		
Scheme / Programme: MAINTENANCE		
Package No:		
Status of the Project: Ongoing/Completed/Under Maintenance		Road Id No:
Work is a case of: New Connectivity/ Up gradation/ Maintenance		
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	
b)	Condition of Surfacing	SRI
c)	Riding Quality	SRI
d)	Road Camber	SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	SRI
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N/A U
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

Asinla
28/12/17
(Signature)

NAME: Deepak C. Sinha
DESIGNATION : J-E