

FIELD INSPECTION REPORT

Date of Inspection: 26-12-2020 District: Nalanda
 Division: H.E.C. Length (km): 0.560 km
 Name of the Road: Ayloupa Parachaya Underpass Road to Babhundi Chowk
 Scheme/Programme: MAINTENANCE Road Id No.:
 Package No.:
 Status of the Project: Ongoing/Completed/Under Maintenance ✓
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
a)	Condition of Surfacing	✓ S
a)	Riding Quality	✓ S
a)	Road Camber	✓ S
a)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
a)	Contractor's joints provided or not (CC Pavement)	✓ Yes/No
a)	Compaction of flank/slope & inlets if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Home pipe culverts including its panning	✓ S
a)	Condition of Abutments & Wing walls Slab in RCC culverts	S/SRI N/A
a)	Condition of abutments Slab approach for Bridges	S/SRI N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 20m/30m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Source of ATR's & any others	NO ATR

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Ram
 26-12-2020
 (Signature)

Ram Choudhary