


FIELD INSPECTION REPORT

Date of Inspection : 06.01.2021		District : Katihar
Division : Katihar		Length (Km) : 1.08 Km
Name of the Road : Dirabasa to Dirachandpur East		
Scheme/Programme :	Maintenance MINHAS (NDB) BRICS	
Package No. :	Road ID No. :	
Status of the Project :	☒ Ongoing/Completed/Under Maintenance	
Work is a case of :	☒ New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be Checked	Remarks
1)	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No
g)	Compaction of Flank/Slope & Raincuts if any	☒ Yes/No
2)	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U N/A
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U / N/A
3)	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	☒ Yes/No
4)	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	—
	Unsatisfactory (U)	—

Name : PAPPU KUMAR
 Designation : J.E
 RWD, Works Division, Katihar.


 06.01.2021
 (Signature)