FIELD INSPECTION REPORT

| Date of Inspection: 06.01.2021 | | | District : Katihar | |
|--|---|----|--------------------|--------------------------|
| Division: Katihar Length (Km): 1.23 KM | | | | |
| Name of the Road: Pokhariya chowk to paswan tola | | | | |
| Scheme/Programme: Maintenance MMGSY (NDB) BRICS | | | | |
| Package No.: Road ID No.: | | | | |
| Status of | Status of the Project : Ongoing/Completed/Under Maintenance | | | |
| Work is a case of: New Connectivity/Up gradation/Maintenance | | | | |
| SLNo. (Remarks Remarks | | | | |
| T | Pavement | | | |
| a) | Road Junction condition | | | ✓S/U |
| b) | Condition of Surfacing | | | √S/U |
| c) | Riding Quality | | | √S/U |
| d) | Road Camber | | | √8/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| g) | Compaction of Flank/Slope & Raincuts if any | | | Yes/No |
| 32). | <u>Cross Drainage</u> | | | |
| a) | Condition of Head walls in Hume Pipe Culverts including its painting | | | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts. | | | S/SRI/U N/A |
| c) | Condition of Railings/Slab/Approach for Bridges | | | S/SRI/U N/A |
| 3), | RoadFurniture | | | patence in this top. The |
| a) | Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained | | | Yes/No |
| .2.4); | | | | K.Z |
| a) | Status of ATR's & | NO | | |
| Overall Pating Catinfactory (S) | | | | |
| Overall Rating : Satisfactory (S) | | | | |
| Satisfactory but requires Improvement (SRI) | | | | |

Name: PAPPU KUMAR

Unsatisfactory (U)

Degisnation: \mathcal{J}, \mathcal{E}

RWD, Works Division, Katihar.

06.01.2021 T. E (Signature)