

# FIELD INSPECTION REPORT

Date of Inspection: 03/01/2021

Division: Dhamdaha.

Name of the Road: Mondal 706a

District: Purnea.

Length (km): Joduke TO 6043

Scheme/Programme: MAINTENANCE

Package No.:

Status of the Project:

Road Id No.:  
Ongoing/Completed/Under Maintenance  
New Connectivity/Up gradation/ Maintenance

Work is a case of:

Parameters to be checked

| Sl. No. | Parameters to be checked                                                                                             | Remarks |
|---------|----------------------------------------------------------------------------------------------------------------------|---------|
| 1.      | Pavement                                                                                                             |         |
| a)      | Road Junction condition                                                                                              | ✓       |
| b)      | Condition of Surfacing                                                                                               | ✓       |
| c)      | Riding Quality                                                                                                       | S/U     |
| d)      | Road Camber                                                                                                          | S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | S/U     |
| f)      | Contraction joints provided or not (CC Pavement)                                                                     | Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No  |
| 2.      | Cross Drainage                                                                                                       | Yes/No  |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U |
| 3.      | Road Furniture                                                                                                       | N/A     |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained | Yes/No  |
| 4.      | Compliance History                                                                                                   |         |
| a)      | Status of ATR's & any others                                                                                         | No ATR  |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | —   |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          | —   |

NAME: Kamal Karyan Sharma  
Junior Engineer

03/1/2021  
(Signature)