

FIELD INSPECTION REPORT

Date of Inspection: 8-1-21	District: GAYA	
Division: Khatmohar/Bathani	Length (Km.): 0.500	
Scheme/Programme:	MAINTENANCE	
Package No.: Jagajhachak to Shadi Pur Road	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
1	Payment	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SR1 S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SR/U
c)	Condition of railings/slab/approach for Bridges	NA S/SR/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Boarding & other signs/Pavement road markings are provided and maintained	Yes Yes/No
4	Compliance History	
a)	Status of ATR's & any others.	NO ATR

Overall Rating :

Satisfactory (S)	SR1
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

checked by
8-1-21
J.E