FIELD INSPECTION REPORT

	of Inspection : (06 01 2021	District: East Champo	1747)
	ion: Works D	ivn DHAKA	Length (km): 2:29 km	ara Mal
	of the Road: Po	MAINTENANCE	100	Sampane
The company of the contract of	ne/Programme:	MAINTENATOR	Road Id No.: 317086	
	ge No.: of the Project:	Ongoing/Complete	d/Under Maintenance	16.03910
	is a case of:	New Connectivity/	Up gradation/ Maintenance	
SL No.		Parameters to be checked		Remarks
1,	Payement			an mandast war as
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			√S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Gross Draining	0	Andrea Anton	Service Schooling
a)	Condition of head walls in Hume pipe culverts including its painting			√S/SRI/U
p) .	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
	Road Furnitur			inangan or da
1)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
用程	elomolinic vil	story	Deling the second of the secon	down't grandle
)	Status of ATR's	& any others		N.A

Overall Rating

Satisfactory (S)	'5'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-

(Signature)

NAME: SANJAY KUMAR OB 01 2021

DESIGNATION: JE JE Chiraiya