

FIELD INSPECTION REPORT

| | | | |
|---|---|---|-------|
| Date of Inspection : 17/12/20 | | District : Bhagalpur | |
| Division : Bhagalpur | | Length (Km) : 0.250 | |
| Name of the Road : ShahKund Asarganj Road to Bhattachak | | | |
| Scheme / Programme : | | MMHCT (SC) | |
| Package No. : | | Road Id No. : 20703201365 | |
| Status of the Project: | | Ongoing / Completed / Under Maintenance | |
| Work is a case of : | | New Connectivity / Up gradation / Maintenance | |
| SL. No. | Parameters to be checked | Remarks | |
| 1. | Pavement | | |
| a) | Road Junction condition | ✓ S / U | |
| b) | Condition of Surfacing | ✓ S / U | |
| c) | Riding Quality | ✓ S / U | |
| d) | Road Camber | ✓ S / U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓ Yes / No | |
| f) | Contraction Joints provided or not (CC Pavement) | ✓ Yes / No | |
| g) | Cmpaction of flank/slope & raincuts if any | ✓ Yes / No | |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S / SRI / U | { n/a |
| b) | Condition of Abutment & Wing Walls, Slab in RCC culverts | S / SRI / U | |
| c) | Condition of railings/slab/approach for Bridges | S / SRI / U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained. | ✓ Yes / No | |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | | |
| Overall Rating : | | | |
| | Satisfactory (S) | 'S' | |
| | Satisfactory but requires Improvement (SRI) | | |
| | Unsatisfactory (U) | | |

Note :

NAME : NEERAJ KUNAR

rd