

FIELD INSPECTION REPORT

Date of Inspection : 30.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 1.240km	
Name of the Road : PMGSY khutaha road to mandal tola			
Scheme / Programme :			
Package No. : MMGSY (SC)		Road Id No. : 20708201367	
Status of the Project : Ongoing / Completed / Under Maintenance ✓			
Work is a case of : New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Cmpaction of flank/slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	
Overall Rating			
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)		

Note: (1) Flank के दोनो सफे माती हो गमाई है
 (2) Culvert के paint 29/11/2020 हो गमाई है

NAME: Ratishor Rajak
 DESIGNATION: A.E


 30.12.2020
 Signature