


FIELD INSPECTION REPORT

| | | | |
|--|--|---|-----------------|
| Date of Inspection : 01/01/2021 | | District : Munger | |
| Division : Munger | | Length (km): 0.500 | |
| Name of the Road : Dharbanga Prachant Andargat Tola Bangalura se Rambur Pak. | | | |
| Scheme/Programme : MAINTENANCE | | G.T.S.N.Y | |
| Package No.: | | Road Id No.: | |
| Status of the Project: | | Ongoing/Completed/Under Maintenance | |
| Work is a case of : | | New Connectivity/Up gradation/Maintenance | |
| Sl.No. | Parameters to be checked | | Remarks |
| 1 | Pavement | | |
| a) | Road Junction condition | | ✓ S / U |
| b) | Condition of Surfacing | | ✓ S / U |
| c) | Riding Quality | | ✓ S / U |
| d) | Road Camber | | ✓ S / U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | ✓ Yes / No |
| f) | Contraction Joints provided or not(CC Pavement) | | ✓ Yes / No |
| g) | Compaction of flank/slope & raincuts if any | | ✓ Yes / No |
| 2 | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | ✓ S / SRI / U |
| b) | Condition of Abutment & Wing walls Slab in Rcc culverts | | S / SRI / U N/A |
| c) | Condition of railings/slab/approach for Bridges | | S / SRI / U N/A |
| 3 | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | ✓ Yes / No |
| 4 | Compliance Histroy | | |
| a) | Status of ATR's & any others | | |

Overall Rating :

| | | |
|---|---|-----|
| Satisfactory (S) | ✓ | 'S' |
| Satisfactory but requires Improvement (SRI) | | |
| Unsatisfactory (U) | | |


 (Signature) 01/01/2021

NAME : MD. Altaf Anwar
 DESIGNATION : J. E.